



**COMPLETION
& PRODUCTION
SERVICES CO.**

CORRELATION LOG

<<< Fold Here >>>


All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.


Comments

THANK YOU FOR USING NABORS COMPLETION & PRODUCTION SERVICES COMPANY
HAYS, KANSAS (785) 628-6395
DIRECTIONS
CLAFIN, KS. E TO RICE COUNTY LINE - 3/4 E. - S & E. INTO

Database File: 10964grocl.db
Dataset Pathname: pass3
Presentation Format: gr-n-ocl
Dataset Creation: Wed Apr 17 12:50:49 2013 by Log Std Casedhole 08121
Charted by: Depth in Feet scaled 1:240

Charted by: _____ Depth in Feet scaled 1:2.15					
0	GAMMA RAY (GAPI)	150	5	CCL	-5






2700

2750


2800

2850

2900



← NOT A COLLAR





2950

3000

3050

3100





3150


3200

GAMMA RAY

GAMMA RAY (GAPI)

0

150



Casing Collars

3229.5 TD REACHED

CCL

-5