

Comments:
Acoustic Cement Bond Log run in combination with Gamma Ray, Neutron, Density and Caliper.
A free interpretation, and a full set of curves from each pass is either displayed on our QC monitor or transmitted for the duration of the job. Although, to the best of our knowledge, the interpretations and opinions expressed are correct, we cannot guarantee the accuracy or correctness of any interpretation and we shall not be responsible for any loss, costs, damages or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our standard terms and conditions as set out in our current Price Schedule.

Comments:

old 40 to 1830ft location on southside rd

Calibration Report

Database File: jose@cromcrs.db
Database Tablename: Gamma
Presentation Format: Log Ver 12.10.2013 Ecs, Log Rm Classifiede 15371

Gamma Ray Calibration Report

Serial Number	38CG
Tool Model	GR
Calibration Date	Thu Mar 14 15:47:46 2013
Calibration Value	200.0 GAPI
Background Reading	23.3 cps
Calibration Reading	174.3 cps
Sensitivity	1.4CPS GAPI/cps

Cement Bond Log Calibration Report

Service Order	10000
Tool Model	CBRT-DL
Calibration Date	Wed Jul 16 16:56:30 2014
Depth	0 m
Casing Diameter	9.625 in
	4
	7 Spacing
Digital Gain	1 (1)
Digital Offset	0.000000
Analog Gain	1.000000
Offset	0.0 (1)
Gain	1.000000
Offset	0.0 (1)

	4.0
	7 Spacing
	1 (1)
	0.000000
	1.000000
	90 (180)
	1 (200)