



Pioneer Energy Services

Microresistivity
Log

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.


Comments

Thank you for using Pioneer Energy Services
785.625.3858


Gove,
South to I Rd, 11 West, 1 1/2 North,
East into


Database File	palomino_rsss #1hd.db
Dataset Pathname	dil/pastkml
Presentation Format	micro
Dataset Creation	Fri Mar 27 01:59:25 2015
Charted by	Depth in Feet scaled 1:240

0	Gamma Ray	150
6	MCAL (GAPI)	16
2.875	Mud Cake (GAPI)	7.875
-200	SP (mV)	0



0	Micro Inverse 1 X 1	40
0	Micro Normal 2"	40
10000	Line Weight	0
		LSPD






3700


3750

3800

3850

3900







3950

4000

4050

4100






4150

4200

4250

4300

4350




-33

-32

-33

-32

-32





4400

4450


4500

4550





0	Gamma Ray	150
6	MCAL (GAPI)	16
2.875	Mud Cake (GAPI)	7.875
-200	SP (mV)	0



0	Micro Inverse 1 X 1	40
0	Micro Normal 2"	40
10000	Line Weight	0

LSPD