



MIDWEST SURVEYS
LOGGING - PERFORATING - CONSULTING SERVICES
P.O. Box 86, Ossawatimille, KS 66064
913 / 756 - 2128

GAMMA RAY / NEUTRON / CCL

File No.

Company Lakeshore Operating, LLC.

Well Bailey Farms No. LO-1

Field Neodesha

County Wilson

State Kansas

Location

1800' FNL & 165' FWL

SW-NW-SW-NW

Sec. 24

Twp. 30S

Rge. 16E

Permian Datum

Log Measured From

Drilling Measured From

GL

GL

Elevation

802'

KB NA

DF NA

GL 802'

Other Services

Perforate

Date

09-19-2017

Run Number

One

Depth Driller

1223.0

Depth Logger

1214.0

Bottom Logged Interval

1213.0

Top Log Interval

20.0

Fluid Level

Full

Type Fluid

Water

Density / Viscosity

NA

Salinity - PPM Cl

NA

Max Recorded Temp

NA

Estimated Cement Top

0.0

Equipment No.

104

Location

Ossawatimie

Recorded By

Gary Windham

Witnessed By

Wesley Ketchum

Run

BORE-HOLE RECORD

TO

FROM

SIZE

WGT.

FROM

TO

No.

BIT

One

9.875"

Two

5.875"

42.0

17.0

1223.0

2.875"

6.5

0.0

42.0

1216.0


<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments

Drilling Contractor :
Leis Oilfield Services, LLC.

Database File: bailey farms 1-lo.db
Dataset Pathname: pass1
Presentation Format: gr-n-ccl
Dataset Creation: Tue Sep 19 12:39:57 2017 by Log SCH 111116
Charted by: Depth in Feet scaled 1:240



10-11-2017
Perforated Interval
981.0 - 1001.0 42 Perfs
2" DML RTG 120° Phase